Use Attainability Analysis

for

WBID 0482 Wildcat Creek

Submitted by
TetraTech Inc.

To
Missouri Department of Natural Resources
Water Protection Program

Field Data Sheets for Recreational Use Stream Surveys

Data Sheet A - Water Body Identification

Water Body Name: (from USGS 7.5' quad)	Wildcat Creek
8-digit HUC:	10280101
Missouri WBID #:	0482
County:	Nodaway
Upstream Legal Description:	NA
Downstream Legal Description:	NA
Upstream Coordinates: (UGS 84, ddd.ddddd)	40.31815° N 94.653810° W
Downstream Coordinates: (UGS 84, ddd.ddddd)	40.21249° N 94.47936° W
Discharger Facility Name(s):	Benedictine Convent
Discharger Permit Number(s):	NA
Number of Sites Evaluated:	6
Name of Surveyor and Telephone Number:	DW, SP, 410-356-8993
Organization:	Tetra Tech, Inc
Position:	Scientist

I, the undersigned, hereby affirm to the best of my knowledge, that all information reported on this UAA datasheet is true and accurate.

Signed: [signature] **Date:** 7-6-05

DW 7/6/05

Wildcat Creek



Field Data Sheets for Recreational Use Stream Surveys

Data Sheet B - Site Characterization

(A separate data sheet must be completed for each site) 310

Missouri WBID #: 0482	Site Location Description: Bridge crossing between Rt 350 & 48a
Site GPS Coordinates: 40.31249°N 94.47736°W	
Date & Time: 1639 7/6/05	Facility Name: Benedictine Convent
Personnel: SP, DW	Permit Number: NA
Current Weather Conditions: Hot, Sunny	Weather Conditions for Past 7 days: Dry, warm
Photo Ids: Upstream: 16 Downstream: 17	Other: NA

Uses Observed*:

☐ Swimming	☐ Skin diving	☐ SCUBA diving	☐ Tubing	☐ Water skiing
☐ Wind surfing	☐ Kayaking	☐ Boating	☐ Wading	☐ Rafting
☐ Hunting	☐ Trapping	☐ Fishing	☒ None of the above	☐ Other:

Describe: (include number of individuals recreating, frequency of use, photo-documentation of evidence of recreational uses, etc.)

Surrounding Conditions*: (Mark all that promote or impede recreational uses. Attach photos of evidence or unusual items of interest.)

☐ City/county parks	☐ Playgrounds	☐ MDC conservation lands	☐ Urban areas	☐ Campgrounds
☐ Boating accesses	☐ State parks	☐ National forests	☐ Nature trails	☐ Stairs/walkway
☐ No trespass sign	☐ Fence	☐ Steep slopes	☒ Other: Ag Fields	

Evidence of Human Use*:

☐ Roads	☐ Foot paths/prints	☐ Dock/platform	☐ Livestock Watering	☐ RV / ATV Tracks
☐ Rope swings	☐ Camping Sites	☐ Fire pit/ring	☐ NPDES Discharge	☐ Fishing Tackle
☐ Other:				

None N/A

Site Locations Map(s): Attach a map of entire segment with assessment sites clearly labeled. Mark any other items that may be of interest. (Include photographs)

*Some of this information is not intended to directly influence a decision on any one particular recreational use analysis but may point to conditions that need further analysis or that effect another use.

Page Two – Data Sheet B for WBID # 0482 :
[310]

Stream Morphology:

Upstream View Physical Dimensions:

☐ Riffle	Width (ft):	Length (ft):	Avg. Depth (ft):	Max. Depth (ft):
☒ Run	Width (ft): 30	Length (ft): 10	Avg. Depth (ft): 0.2	Max. Depth (ft): 0.33
☐ Pool	Width (ft):	Length (ft):	Avg. Depth (ft):	Max. Depth (ft):
☒ Flow	Present? ☒ Yes ☐ No		~~Estimated (ft³/sec):~~ 3 ft/sec	

JW 7/6

Downstream View Physical Dimensions: Braided Stream 60' width Total

☐ Riffle	Width (ft):	Length (ft):	Avg. Depth (ft):	Max. Depth (ft):
☐ Run	Width (ft):	Length (ft):	Avg. Depth (ft):	Max. Depth (ft):
☒ Pool	Width (ft):	Length (ft): 10	Avg. Depth (ft): 1.33	Max. Depth (ft): 2
☒ Flow	Present? ☒ Yes ☐ No		Estimated (ft³/sec): Negligent, not measurable	

Substrate*: (These values should add up to 100%.)

% Cobble	% Gravel	% Sand	% Silt	% Mud/Clay	% Bedrock
5	70		25		

Aquatic Vegetation*: (note amount of vegetation or algal growth at the assessment site)

NONE

Water Characteristics*: (Mark all that apply.)

Odor:	☐ Sewage	☐ Musky	☐ Chemical	☒ None	☐ Other:
Color:	☒ Clear	☐ Green	☐ Gray	☐ Milky	☐ Other:
Bottom Deposit:	☐ Sludge	☐ Solids	☐ Fine sediments	☒ None	☐ Other:
Surface Deposit:	☐ Oil	☐ Scum	☒ Foam → small amount	☐ None	☐ Other:

Comments: Please attach additional comments (including information from interviews) to this form.

*This information is not to be used solely for removal of a recreational use designation but rather as to provide a more comprehensive understanding of water conditions. Consequently, this information is not intended to directly influence a decision on the recreation use analysis but may point to conditions that need further analysis or that effect another use.

I, the undersigned, hereby affirm to the best of my knowledge, that all information reported on this UAA datasheet is true and accurate.

Signed: [signature] **Date:** 7-6-05

Organization: Tetra Tech Position: Scientist

JW 7/6/05

0482_310_US

0482_310_DS

Field Data Sheets for Recreational Use Stream Surveys

Data Sheet B - Site Characterization

(A separate data sheet must be completed for each site)

Missouri WBID #: 0482		Site Location Description: Bridge @ CR430	
Site GPS Coordinates: 40.21758 °N 94.57567 °W			
Date & Time: 1550 7/6/05		Facility Name: Grindstone Convent	
Personnel: SP, DW		Permit Number: NA	
Current Weather Conditions: 141 Sunny		Weather Conditions for Past 7 days: Dry, low 141	
Photo Ids: Upstream: 14	Downstream: 15	Other: NA	

Uses Observed*:

☐ Swimming	☐ Skin diving	☐ SCUBA diving	☐ Tubing	☐ Water skiing
☐ Wind surfing	☐ Kayaking	☐ Boating	☐ Wading	☐ Rafting
☐ Hunting	☐ Trapping	☐ Fishing	☒ None of the above	☐ Other:

Describe: (include number of individuals recreating, frequency of use, photo documentation of evidence of recreational uses, etc.)

Surrounding Conditions*: (Mark all that promote or impede recreational uses. Attach photos of evidence or unusual items of interest.)

☐ City/county parks	☐ Playgrounds	☐ MDC conservation lands	☐ Urban areas	☐ Campgrounds
☐ Boating accesses	☐ State parks	☐ National forests	☐ Nature trails	☐ Stairs/walkway
☐ No trespass sign	☒ Fence to upstream side	☒ Steep slopes	☒ Other: Ag Fields	

Evidence of Human Use*:

☒ Roads	☐ Foot paths/prints	☐ Dock/platform	☐ Livestock Watering	☐ RV / ATV Tracks
☐ Rope swings	☐ Camping Sites	☐ Fire pit/ring	☐ NPDES Discharge	☐ Fishing Tackle
☐ Other:				

Site Locations Map(s): Attach a map of entire segment with assessment sites clearly labeled. Mark any other items that may be of interest. (Include photographs)

*Some of this information is not intended to directly influence a decision on any one particular recreational use analysis but may point to conditions that need further analysis or that effect another use.

Page Two – Data Sheet B for WBID # 0482 :

311

Stream Morphology:

~~Upstream~~ DOWNSTREAM View Physical Dimensions:

Down Stream

☐ Riffle	Width (ft):		Length (ft):		Avg. Depth (ft):		Max. Depth (ft):	
☒ Run	Width (ft):	15	Length (ft):	10	Avg. Depth (ft):	0.5	Max. Depth (ft):	0.66
☐ Pool	Width (ft):		Length (ft):		Avg. Depth (ft):		Max. Depth (ft):	
☒ Flow	Present?	☒ Yes	☐ No		Estimated (ft^3/sec):	5'/20 s		

Dw 7/6

~~Downstream~~ UPSTREAM View Physical Dimensions:

☐ Riffle	Width (ft):		Length (ft):		Avg. Depth (ft):		Max. Depth (ft):	
☒ Run	Width (ft):	20	Length (ft):	10	Avg. Depth (ft):	0.33	Max. Depth (ft):	0.66
☐ Pool	Width (ft):		Length (ft):		Avg. Depth (ft):		Max. Depth (ft):	
☒ Flow	Present?	☒ Yes	☐ No		Estimated (ft^3/sec):	5'/30 s		

Substrate*: (These values should add up to 100%.)

10	% Cobble	30	% Gravel	50	% Sand		% Silt	10	% Mud/Clay		% Bedrock

Aquatic Vegetation*: (note amount of vegetation or algal growth at the assessment site)

UPSTREAM & ALGAE (5%)
Downstream

Water Characteristics*: (Mark all that apply.)

Odor:	☐ Sewage	☒ Musky	☐ Chemical	☐ None	☐ Other:
Color:	☒ Clear	☐ Green	☐ Gray	☐ Milky	☐ Other:
Bottom Deposit:	☐ Sludge	☐ Solids	☐ Fine sediments	☒ None	☐ Other:
Surface Deposit:	☐ Oil	☐ Scum	☐ Foam	☒ None	☐ Other:

Comments: Please attach additional comments (including information from interviews) to this form.

*This information is not to be used solely for removal of a recreational use designation but rather is to provide a more comprehensive understanding of water conditions. Consequently, this information is not intended to directly influence a decision on the recreation use analysis but may point to conditions that need further analysis or that effect another use.

I, the undersigned, hereby affirm to the best of my knowledge, that all information reported on this UAA datasheet is true and accurate.

Signed: [signature] **Date:** 7-6-05

Organization: Tetra Tech **Position:** Scientist

DW 7/6/05

0482_311_US

0482_311_DS

Field Data Sheets for Recreational Use Stream Surveys

Data Sheet B - Site Characterization

(A separate data sheet must be completed for each site) 3/2

Missouri WBID #: 0782		Site Location Description: Bridge @ CR 320	
Site GPS Coordinates: 40.25673 °N 94.6828 °W			
Date & Time: 3:00 P 7/6/05		Facility Name: Bandicoot Corner	
Personnel: SP, DW		Permit Number: N/A	
Current Weather Conditions: Hot Sunny		Weather Conditions for Past 7 days: Dry, Sunny	
Photo Ids: Upstream: 12	Downstream: 13	Other: N/A	

Uses Observed*:

☐ Swimming	☐ Skin diving	☐ SCUBA diving	☐ Tubing	☐ Water skiing
☐ Wind surfing	☐ Kayaking	☐ Boating	☐ Wading	☐ Rafting
☐ Hunting	☐ Trapping	☐ Fishing	☒ None of the above	☐ Other:

Describe: (include number of individuals recreating, frequency of use, photo-documentation of evidence of recreational uses, etc.)

Surrounding Conditions*: (Mark all that promote or impede recreational uses. Attach photos of evidence or unusual items of interest.)

☐ City/county parks	☐ Playgrounds	☐ MDC conservation lands	☐ Urban areas	☐ Campgrounds
☐ Boating accesses	☐ State parks	☐ National forests	☐ Nature trails	☐ Stairs/walkway
☐ No trespass sign	☐ Fence	☒ Steep slopes	☒ Other: Ag. Fields	

Evidence of Human Use*:

☒ Roads	☐ Foot paths/prints	☐ Dock/platform	☐ Livestock Watering	☐ RV / ATV Tracks
☐ Rope swings	☐ Camping Sites	☐ Fire pit/ring	☐ NPDES Discharge	☐ Fishing Tackle
☐ Other:				

Site Locations Map(s): Attach a map of entire segment with assessment sites clearly labeled. Mark any other items that may be of interest. (Include photographs)

*Some of this information is not intended to directly influence a decision on any one particular recreational use analysis but may point to conditions that need further analysis or that effect another use.

Page Two – Data Sheet B for WBID # 0482 : 312

Stream Morphology:

Upstream View Physical Dimensions:

☐ Riffle	Width (ft):	Length (ft):	Avg. Depth (ft):	Max. Depth (ft):
☒ Run	Width (ft): 15	Length (ft): 10	Avg. Depth (ft): 1.75	Max. Depth (ft): 2'
☐ Pool	Width (ft):	Length (ft):	Avg. Depth (ft):	Max. Depth (ft):
☐ Flow	Present? ☒ Yes ☐ No		Estimated (ft^3/sec): present, not measurable	

Downstream View Physical Dimensions:

☐ Riffle	Width (ft):	Length (ft):	Avg. Depth (ft):	Max. Depth (ft):
☒ Run	Width (ft): 20	Length (ft): 10	Avg. Depth (ft): 1	Max. Depth (ft): 1.5
☐ Pool	Width (ft):	Length (ft):	Avg. Depth (ft):	Max. Depth (ft):
☒ Flow	Present? ☒ Yes ☐ No		Estimated (ft^3/sec): yes, too slow to measure	

Substrate*: (These values should add up to 100%.) DW 7/6

10 % Cobble	% Gravel	50 % Sand	% Silt	~~30~~ 40 % Mud/Clay	% Bedrock

Aquatic Vegetation*: (note amount of vegetation or algal growth at the assessment site)

None Upstream
Algae Downstream (10%)

Water Characteristics*: (Mark all that apply.)

Odor:	☐ Sewage	☐ Musky	☐ Chemical	☒ None	☐ Other:
Color:	☐ Clear	☒ Green	☐ Gray	☐ Milky	☐ Other:
Bottom Deposit:	☐ Sludge	☐ Solids	☐ Fine sediments	☒ None	☐ Other:
Surface Deposit:	☐ Oil	☒ Scum SLIGHT	☐ Foam	☐ None	☐ Other:

Comments: Please attach additional comments (including information from interviews) to this form.

*This information is not to be used solely for removal of a recreational use designation but rather is to provide a more comprehensive understanding of water conditions. Consequently, this information is not intended to directly influence a decision on the recreation use analysis but may point to conditions that need further analysis or that effect another use.

I, the undersigned, hereby affirm to the best of my knowledge, that all information reported on this UAA datasheet is true and accurate.

Signed: [signature] **Date:** 7-6-05

Organization: Tetra Tech Position: Scientist

DW 7/6/05

0482_312_US

0482_312_DS

Field Data Sheets for Recreational Use Stream Surveys

Data Sheet B - Site Characterization

(A separate data sheet must be completed for each site) 313

Missouri WBID #: 0762	Site Location Description: NEAR 310 & Pauther Intersection Stream @ 310 Bridge King
Site GPS Coordinates: 40.29120°N 91.63235°W	
Date & Time: 250 P 7/6/05	Facility Name: Benedictine Convent
Personnel: SP, DW	Permit Number: N/A
Current Weather Conditions: Hot, Sunny	Weather Conditions for Past 7 days: Hot, Dry
Photo Ids: Upstream: 8 Downstream: 11	Other: 9 (Fence) 10 (Hoof Prints) Cattle

Uses Observed*:

☐ Swimming	☐ Skin diving	☐ SCUBA diving	☐ Tubing	☐ Water skiing
☐ Wind surfing	☐ Kayaking	☐ Boating	☐ Wading	☐ Rafting
☐ Hunting	☐ Trapping	☐ Fishing	☒ None of the above	☐ Other:

Describe: (include number of individuals recreating, frequency of use, photo-documentation of evidence of recreational uses, etc.)

Surrounding Conditions*: (Mark all that promote or impede recreational uses. Attach photos of evidence or unusual items of interest.)

☐ City/county parks	☐ Playgrounds	☐ MDC conservation lands	☐ Urban areas	☐ Campgrounds
☐ Boating accesses	☐ State parks	☐ National forests	☐ Nature trails	☐ Stairs/walkway
☐ No trespass sign	☒ Fence	☒ Steep slopes	☒ Other: Agricultural Fields	

Evidence of Human Use*:

☒ Roads	☐ Foot paths/prints	☐ Dock/platform	☒ Livestock Watering	☐ RV / ATV Tracks
☐ Rope swings	☐ Camping Sites	☐ Fire pit/ring	☐ NPDES Discharge	☐ Fishing Tackle
☐ Other:				

Site Locations Map(s): Attach a map of entire segment with assessment sites clearly labeled. Mark any other items that may be of interest. (Include photographs)

*Some of this information is not intended to directly influence a decision on any one particular recreational use analysis but may point to conditions that need further analysis or that effect another use.

Page Two – Data Sheet B for WBID # 0482 :

(313)

Stream Morphology:

Upstream View Physical Dimensions:

☐ Riffle	Width (ft):		Length (ft):		Avg. Depth (ft):		Max. Depth (ft):
☒ Run	Width (ft):	10	Length (ft):	10	Avg. Depth (ft):	0.1	Max. Depth (ft): 0.3
☐ Pool	Width (ft):		Length (ft):		Avg. Depth (ft):		Max. Depth (ft):
☒ Flow	Present?	☒ Yes ☐ No			Estimated ~~(ft³/sec)~~:	V*	1'/1 sec (ft/sec)

dw 7/6

Downstream View Physical Dimensions:

☐ Riffle	Width (ft):		Length (ft):		Avg. Depth (ft):		Max. Depth (ft):
☒ Run	Width (ft):	3.5'	Length (ft):	10	Avg. Depth (ft):	0.25	Max. Depth (ft): 0.3
☐ Pool	Width (ft):		Length (ft):		Avg. Depth (ft):		Max. Depth (ft):
☒ Flow	Present?	☒ Yes ☐ No			Estimated ~~(ft³/sec)~~:	5'/8 s	(ft/sec)

dw 7/6

Substrate*: (These values should add up to 100%.)

% Cobble	% Gravel	% Sand	% Silt	% Mud/Clay	% Bedrock
10	15			65	

Aquatic Vegetation*: (note amount of vegetation or algal growth at the assessment site)

NONE

Water Characteristics*: (Mark all that apply.)

Odor:	☐ Sewage	☐ Musky	☐ Chemical	☐ None	☒ Other: Manure
Color:	☐ Clear	☐ Green	☐ Gray	☐ Milky	☒ Other: Slightly Cloudy
Bottom Deposit:	☐ Sludge	☐ Solids	☐ Fine sediments	☒ None	☐ Other:
Surface Deposit:	☐ Oil	☐ Scum	☐ Foam	☒ None	☐ Other:

Comments: Please attach additional comments (including information from interviews) to this form.

*This information is not to be used solely for removal of a recreational use designation but rather is to provide a more comprehensive understanding of water conditions. Consequently, this information is not intended to directly influence a decision on the recreation use analysis but may point to conditions that need further analysis or that effect another use.

I, the undersigned, hereby affirm to the best of my knowledge, that all information reported on this UAA datasheet is true and accurate.

Signed: [illegible] **Date:** 7-6-05

Organization: Tetra Tech **Position:** Scientist

dw 7/6/05

0482_313_US

0482_313_DS

0482_313_US Fence

0482_313_US Hoofprints

Field Data Sheets for Recreational Use Stream Surveys

Data Sheet B - Site Characterization

(A separate data sheet must be completed for each site) 314

Missouri WBID #: 0482	Site Location Description: Bridge Crossing RL AF
Site GPS Coordinates: 40.28579°N 94.64066°W	
Date & Time: 2:00 PM 7/6/05	Facility Name: Benedictine Convent
Personnel: SP, DW	Permit Number: N/A
Current Weather Conditions: Hot, Sunny	Weather Conditions for Past 7 days: Clear, dry, Sunny
Photo Ids: Upstream: 5 Downstream: 6	Other: 7 (Concrete Debris)

Uses Observed*:

☐ Swimming	☐ Skin diving	☐ SCUBA diving	☐ Tubing	☐ Water skiing
☐ Wind surfing	☐ Kayaking	☐ Boating	☐ Wading	☐ Rafting
☐ Hunting	☐ Trapping	☐ Fishing	☒ None of the above	☐ Other:

Describe: (include number of individuals recreating, frequency of use, photo-documentation of evidence of recreational uses, etc.)

Surrounding Conditions*: (Mark all that promote or impede recreational uses. Attach photos of evidence or unusual items of interest.)

NA

☐ City/county parks	☐ Playgrounds	☐ MDC conservation lands	☐ Urban areas	☐ Campgrounds
☐ Boating accesses	☐ State parks	☐ National forests	☐ Nature trails	☐ Stairs/walkway
☐ No trespass sign	☐ Fence	☐ Steep slopes	☐ Other:	

Evidence of Human Use*:

☒ Roads	☐ Foot paths/prints	☐ Dock/platform	☐ Livestock Watering	☐ RV / ATV Tracks
☐ Rope swings	☐ Camping Sites	☐ Fire pit/ring	☐ NPDES Discharge	☐ Fishing Tackle
☐ Other:				

Site Locations Map(s): Attach a map of entire segment with assessment sites clearly labeled. Mark any other items that may be of interest. (Include photographs)

*Some of this information is not intended to directly influence a decision on any one particular recreational use analysis but may point to conditions that need further analysis or that effect another use.

Page Two – Data Sheet B for WBID # 0782 :

Stream Morphology:

Upstream View Physical Dimensions: 3/4

☐ Riffle	Width (ft):	Length (ft):	Avg. Depth (ft):	Max. Depth (ft):
☒ Run	Width (ft): 20	Length (ft): 10	Avg. Depth (ft): 1.5	Max. Depth (ft): 2
☐ Pool	Width (ft):	Length (ft):	Avg. Depth (ft):	Max. Depth (ft):
☒ Flow	Present? ☒ Yes ☐ No		Estimated (ft^3/sec): not measurable	

Downstream View Physical Dimensions:

☐ Riffle	Width (ft):	Length (ft):	Avg. Depth (ft):	Max. Depth (ft):
☒ Run	Width (ft): 18	Length (ft): 10	Avg. Depth (ft): 0.80	Max. Depth (ft): 1.5
☐ Pool	Width (ft):	Length (ft):	Avg. Depth (ft):	Max. Depth (ft):
☐ Flow	Present? ☒ Yes ☐ No		Estimated (ft^3/sec): 3/gal ~ 0.03 (ft/sec)	

JW 7/6

Substrate*: (These values should add up to 100%.)

10	% Cobble	20	% Gravel		% Sand		% Silt	70	% Mud/Clay		% Bedrock

Aquatic Vegetation*: (note amount of vegetation or algal growth at the assessment site)

<5% algae

Water Characteristics*: (Mark all that apply.)

Odor:	☐ Sewage	☒ Musky	☐ Chemical	☐ None	☐ Other:
Color:	☐ Clear	☐ Green	☐ Gray	☒ Milky	☐ Other:
Bottom Deposit:	☐ Sludge	☐ Solids	☐ Fine sediments	☒ None	☐ Other:
Surface Deposit:	☐ Oil	☐ Scum	☐ Foam	☒ None	☐ Other:

Comments: Please attach additional comments (including information from interviews) to this form.

*This information is not to be used solely for removal of a recreational use designation but rather is to provide a more comprehensive understanding of water conditions. Consequently, this information is not intended to directly influence a decision on the recreation use analysis but may point to conditions that need further analysis or that effect another use.

I, the undersigned, hereby affirm to the best of my knowledge, that all information reported on this UAA datasheet is true and accurate.

Signed: [signature] **Date:** 7-06-05

Organization: Tetra Tech **Position:** Scientist

JW 7/6/05

0482_314_US

0482_314_DS

0482_314_concrete

Field Data Sheets for Recreational Use Stream Surveys

Data Sheet B - Site Characterization

(A separate data sheet must be completed for each site)

315

Missouri WBID #: 0482	Site Location Description: Bridge Crossing @ 277 St
Site GPS Coordinates: 40.31815°N, -94.653816°E	
Date & Time: 1:30 PM 7/6/05	Facility Name: Benedictine Convent
Personnel: DW, SP	Permit Number: N/A
Current Weather Conditions: Hot, Sunny	Weather Conditions for Past 7 days: Clear dry, Sunny
Photo Ids: Upstream: 1 Downstream: 2	Other: 3 (Upstream Fence) 4 (Downstream Fence)

Uses Observed*:

☐ Swimming	☐ Skin diving	☐ SCUBA diving	☐ Tubing	☐ Water skiing
☐ Wind surfing	☐ Kayaking	☐ Boating	☐ Wading	☐ Rafting
☐ Hunting	☐ Trapping	☐ Fishing	☒ None of the above	☐ Other:

Describe: (include number of individuals recreating, frequency of use, photo-documentation of evidence of recreational uses, etc.)

Surrounding Conditions*: (Mark all that promote or impede recreational uses. Attach photos of evidence or unusual items of interest.)

☐ City/county parks	☐ Playgrounds	☐ MDC conservation lands	☐ Urban areas	☐ Campgrounds
☐ Boating accesses	☐ State parks	☐ National forests	☐ Nature trails	☐ Stairs/walkway
☐ No trespass sign	☒ Fence	☐ Steep slopes	☒ Other: Agricult. Fields	

Evidence of Human Use*:

☒ Roads	☐ Foot paths/prints	☐ Dock/platform	☐ Livestock Watering	☐ RV / ATV Tracks
☐ Rope swings	☐ Camping Sites	☐ Fire pit/ring	☐ NPDES Discharge	☐ Fishing Tackle
☐ Other:				

Site Locations Map(s): Attach a map of entire segment with assessment sites clearly labeled. Mark any other items that may be of interest. (Include photographs)

*Some of this information is not intended to directly influence a decision on any one particular recreational use analysis but may point to conditions that need further analysis or that effect another use.

Page Two – Data Sheet B for WBID # 0162 : 315

Stream Morphology:

Upstream View Physical Dimensions: DRY

☐ Riffle	Width (ft):	Length (ft):	Avg. Depth (ft):	Max. Depth (ft):
☐ Run	Width (ft):	Length (ft):	Avg. Depth (ft):	Max. Depth (ft):
☐ Pool	Width (ft):	Length (ft):	Avg. Depth (ft):	Max. Depth (ft):
☐ Flow	Present? ☐ Yes	☒ No	Estimated (ft^3/sec): DRY	

Downstream View Physical Dimensions:

☐ Riffle	Width (ft):	Length (ft):	Avg. Depth (ft):	Max. Depth (ft):
☐ Run	Width (ft):	Length (ft):	Avg. Depth (ft):	Max. Depth (ft):
☒ Pool	Width (ft): 8	Length (ft): 20	Avg. Depth (ft): 0.66	Max. Depth (ft): 1
☐ Flow	Present? ☐ Yes	☒ No	Estimated (ft^3/sec): not measurable	

Substrate*: (These values should add up to 100%.)

15 % Cobble	20 % Gravel	% Sand	% Silt	65 % Mud/Clay	% Bedrock

Aquatic Vegetation*: (note amount of vegetation or algal growth at the assessment site)

NONE

Water Characteristics*: (Mark all that apply.)

Odor:	☐ Sewage	☐ Musky	☐ Chemical	☒ None	☐ Other:
Color:	☐ Clear	☐ Green	☒ Gray	☐ Milky	☐ Other:
Bottom Deposit:	☐ Sludge	☐ Solids	☐ Fine sediments	☒ None	☐ Other:
Surface Deposit:	☐ Oil	☐ Scum	☐ Foam	☒ None	☐ Other:

Comments: Please attach additional comments (including information from interviews) to this form.

*This information is not to be used solely for removal of a recreational use designation but rather is to provide a more comprehensive understanding of water conditions. Consequently, this information is not intended to directly influence a decision on the recreation use analysis but may point to conditions that need further analysis or that effect another use.

I, the undersigned, hereby affirm to the best of my knowledge, that all information reported on this UAA datasheet is true and accurate.

Signed: [signature] **Date:** 7-6-05

Organization: Texas Tech **Position:** Scientist

JW 7/6/05

0482_315_US

0482_315_US fence

0482_315_DS

0482_315_DS fence