Use Attainability Analysis

for

WBID 2121 Tributary to Shibboleth Creek

Submitted by
Missouri Department of Natural Resources Staff

To
Missouri Department of Natural Resources
Water Protection Program

RECEIVED

2005 JUN 13 AM 11: 50

WATER PROTECTION PROGRAM

Field Data Sheets for Recreational Use Stream Surveys

Data Sheet A - Water Body Identification

Water Body Name (from USGS 7.5' quad):	Tributary to Shibboleth Creek
8-digit HUC:	~~07140100~~ 07140104
Missouri WBID #:	2121
County:	Washington
Upstream Legal Description:	~~702738~~ Survey 1875 Just NE Sec. 15 T38N R3E
Downstream Legal Description:	~~702895 4210461~~ Sec. 15 T38N R3E
Upstream Coordinates:	UTM 702738 4210643
Downstream Coordinates:	UTM 702895 4210461
Discharger Facility Name(s):	
Discharger Permit Number(s):	
Number of Sites Evaluated:	2 (unable to access other observation points)
Name of Surveyor and Telephone Number:	Tucker Fredrickson (573) 526-4210
Organization:	MDNR
Position:	Environmental Specialist

I, the undersigned, hereby affirm to the best of my knowledge, that all information reported on this UAA datasheet is true and accurate.

Signed: Tucker Fredrickson **Date:** 6/7/05

7140104 Trib to Shibboleth Crk. - 1 mile # 2121



Field Data Sheets for Recreational Use Stream Surveys

Data Sheet B - Site Characterization

(A separate data sheet must be completed for each site)

Missouri WBID #: 2121-01	Site Location Description: Property of Bill (CR 410) (10364 Hinch Rd.) Tyra #1
Site GPS Coordinates: 702738 4210643	
29.2 Date & Time: 6/7/05 3:30PM	Facility Name: Trib. to Shibboleth Crk.
Personnel: Tucker Fredrickson	Permit Number:
Current Weather Conditions: Sunny 85°F	Weather Conditions for Past 7 days: Less than 1" rainfall
Photo Ids: Upstream: 21 Downstream: 22	Other: H Temp. Range 80-90°F

Uses Observed*:

☐ Swimming	☐ Skin diving	☐ SCUBA diving	☐ Tubing	☐ Water skiing
☐ Wind surfing	☐ Kayaking	☐ Boating	☐ Wading	☐ Rafting
☐ Hunting	☐ Trapping	☐ Fishing	☒ None of the above	☐ Other:

Describe: (include number of individuals recreating, frequency of use, photo-documentation of evidence of recreational uses, etc.)

Surrounding Conditions*: (Mark all that promote or impede recreational uses. Attach photos of evidence or unusual items of interest.)

☐ City/county parks	☐ Playgrounds	☐ MDC conservation lands	☐ Urban areas	☐ Campgrounds
☐ Boating accesses	☐ State parks	☐ National forests	☐ Nature trails	☐ Stairs/walkway
☐ No trespass sign	☐ Fence	☐ Steep slopes	☒ Other: NA	

Evidence of Human Use*:

☐ Roads	☐ Foot paths/prints	☐ Dock/platform	☐ Livestock Watering	☐ RV / ATV Tracks
☐ Rope swings	☐ Camping Sites	☐ Fire pit/ring	☐ NPDES Discharge	☐ Fishing Tackle
☒ Other: NA				

Site Locations Map(s): Attach a map of entire segment with assessment sites clearly labeled. Mark any other items that may be of interest. (Include photographs)

*Some of this information is not intended to directly influence a decision on any one particular recreational use analysis but may point to conditions that need further analysis or that effect another use.

Page Two – Data Sheet B for WBID # 2121 :

Stream Morphology:

Upstream View Physical Dimensions:

☐ Riffle	Width (ft):	Length (ft):	Avg. Depth (ft):	Max. Depth (ft):
☐ Run	Width (ft):	Length (ft):	Avg. Depth (ft):	Max. Depth (ft):
☒ Pool	Width (ft): 15	Length (ft): 70	Avg. Depth (ft): 0.6	Max. Depth (ft): 1.5
☐ Flow	Present? ☒ Yes ☐ No		Estimated (ft^3/sec):	

Downstream View Physical Dimensions:

☐ Riffle	Width (ft):	Length (ft):	Avg. Depth (ft):	Max. Depth (ft):
☐ Run	Width (ft):	Length (ft):	Avg. Depth (ft):	Max. Depth (ft):
☒ Pool	Width (ft): 25	Length (ft): 50	Avg. Depth (ft): 1.25	Max. Depth (ft): 1.75
☐ Flow	Present? ☒ Yes ☐ No		Estimated (ft^3/sec):	

Substrate*: (These values should add up to 100%.)

30 % Cobble	50 % Gravel	% Sand	% Silt	% Mud/Clay	20 % Bedrock

Aquatic Vegetation*: (note amount of vegetation or algal growth at the assessment site)

Water Characteristics*: (Mark all that apply.)

Odor:	☐ Sewage	☐ Musky	☐ Chemical	☒ None	☐ Other:
Color:	☒ Clear	☐ Green	☐ Gray	☐ Milky	☐ Other:
Bottom Deposit:	☐ Sludge	☐ Solids	☐ Fine sediments	☒ None	☐ Other:
Surface Deposit:	☐ Oil	☐ Scum	☐ Foam	☒ None	☐ Other:

Comments: Please attach additional comments (including information from interviews) to this form.

*This information is not to be used solely for removal of a recreational use designation but rather is to provide a more comprehensive understanding of water conditions. Consequently, this information is not intended to directly influence a decision on the recreation use analysis but may point to conditions that need further analysis or that effect another use.

I, the undersigned, hereby affirm to the best of my knowledge, that all information reported on this UAA datasheet is true and accurate.

Signed: Tucker Fredrickson Date: 6/7/05

Organization: MDNR Position: ES

2121_001_US

2121_001_DS

Field Data Sheets for Recreational Use Stream Surveys

Data Sheet B - Site Characterization

(A separate data sheet must be completed for each site)

Missouri WBID #: 2121-02	Site Location Description: Bridge crossing Pvt.
Site GPS Coordinates: 702895 4210461	#2 Property just SW of Hinch Road (CR 410)
Date & Time: 6/7/05 11:00 AM	Facility Name: Trib. to Shibboleth Crk.
Personnel: Tucker Fredrickson	Permit Number:
Current Weather Conditions: Sunny 80°F	Weather Conditions for Past 7 days: Less than 1" rainfall
Photo Ids: Upstream: 13 Downstream: 14	Other: H Temp. Range 80-90°F

Uses Observed*:

☐ Swimming	☐ Skin diving	☐ SCUBA diving	☐ Tubing	☐ Water skiing
☐ Wind surfing	☐ Kayaking	☐ Boating	☐ Wading	☐ Rafting
☐ Hunting	☐ Trapping	☐ Fishing	☒ None of the above	☐ Other:

Describe: (include number of individuals recreating, frequency of use, photo-documentation of evidence of recreational uses, etc.)

NA

Surrounding Conditions*: (Mark all that promote or impede recreational uses. Attach photos of evidence or unusual items of interest.)

☐ City/county parks	☐ Playgrounds	☐ MDC conservation lands	☐ Urban areas	☐ Campgrounds
☐ Boating accesses	☐ State parks	☐ National forests	☐ Nature trails	☐ Stairs/walkway
☐ No trespass sign	☐ Fence	☐ Steep slopes	☒ Other: NA	

Evidence of Human Use*:

☐ Roads	☐ Foot paths/prints	☐ Dock/platform	☐ Livestock Watering	☐ RV / ATV Tracks
☐ Rope swings	☐ Camping Sites	☐ Fire pit/ring	☐ NPDES Discharge	☐ Fishing Tackle
☒ Other: NA				

Site Locations Map(s): Attach a map of entire segment with assessment sites clearly labeled. Mark any other items that may be of interest. (Include photographs)

*Some of this information is not intended to directly influence a decision on any one particular recreational use analysis but may point to conditions that need further analysis or that effect another use.

Page Two – Data Sheet B for WBID # 2121:

Stream Morphology:

Upstream View Physical Dimensions:

☐ Riffle	Width (ft):	Length (ft):	Avg. Depth (ft):	Max. Depth (ft):
☐ Run	Width (ft):	Length (ft):	Avg. Depth (ft):	Max. Depth (ft):
☒ Pool	Width (ft): 15	Length (ft): 40	Avg. Depth (ft): 0.4	Max. Depth (ft): 0.75
☐ Flow	Present? ☒ Yes ☐ No		Estimated (ft^3/sec):	

Downstream View Physical Dimensions:

☐ Riffle	Width (ft):	Length (ft):	Avg. Depth (ft):	Max. Depth (ft):
☒ Run	Width (ft): 15	Length (ft): 15	Avg. Depth (ft): 0.25	Max. Depth (ft): 0.4
☐ Pool	Width (ft):	Length (ft):	Avg. Depth (ft):	Max. Depth (ft):
☐ Flow	Present? ☒ Yes ☐ No		Estimated (ft^3/sec):	

Substrate*: (These values should add up to 100%.)

40 % Cobble	20 % Gravel	% Sand	% Silt	% Mud/Clay	30 % Bedrock

Aquatic Vegetation*: (note amount of vegetation or algal growth at the assessment site)

85% aquatic vegetation coverage - upstream

Water Characteristics*: (Mark all that apply.)

Odor:	☐ Sewage	☐ Musky	☐ Chemical	☒ None	☐ Other:
Color:	☒ Clear	☐ Green	☐ Gray	☐ Milky	☐ Other:
Bottom Deposit:	☐ Sludge	☐ Solids	☐ Fine sediments	☒ None	☐ Other:
Surface Deposit:	☐ Oil	☐ Scum	☐ Foam	☒ None	☐ Other:

Comments: Please attach additional comments (including information from interviews) to this form.

*This information is not to be used solely for removal of a recreational use designation but rather is to provide a more comprehensive understanding of water conditions. Consequently, this information is not intended to directly influence a decision on the recreation use analysis but may point to conditions that need further analysis or that effect another use.

I, the undersigned, hereby affirm to the best of my knowledge, that all information reported on this UAA datasheet is true and accurate.

Signed: Tucker Fredrickson **Date:** 6/7/05

Organization: MDNR Position: ES

2121_002_US

2121_002_DS